

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection: OGM Priscilla Burton Environmental Scientist III Company Patrick D. Collins Resident Agent

Inspection Report

Permit Number:	C0070012		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, October 24, 2006		
Start Date/Time:	10/24/2006 9:00:00 AM		
End Date/Time:	10/24/2006 10:30:00 AM		
Last Inspection:	Monday, September 25, 2006		

Inspector: Priscilla Burton, Environmental Scientist III

Weather: 40 F sun

InspectionID Report Number: 1113

Types of Operations

Accepted by: whedberg

10/26/2006

Permitee: NEVADA ELECTRIC INVESTMENT CO

Operator: NEVADA ELECTRIC INVESTMENT CO
Site: WELLINGTON PREPARATION PLANT

Address: 330 E 400 S STE 6, PO BOX 337 SPRINGVILLE UT 84663

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Ac	reages
------------	--------

1,573.50	Total Permitted		
392.00	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral	Ownership
---------	-----------

☐ Federal ☐ Underground ☐ State ☐ Surface ☐ County ☐ Loadout ☐ Processing ☐ Other ☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Site has received a lot of rain during the month. All ponds are holding water. Ditch UD-1 is ponding water as well.

Inspector's Signature:

Priselle Button Endouverent Scientist III

Date

Tuesday, October 24, 2006

Priscilla Burton, Environmental Scientist III

Inspector ID Number: 37

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Inspection Continuation Sheet

Permit Number: C0070012 Inspection Type: PARTIAL

Inspection Date: Tuesday, October 24, 2006

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	✓		\checkmark	
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls	V		✓	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070012 Inspection Type: PARTIAL

Inspection Date: Tuesday, October 24, 2006

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

Assessment Conference for NOV #N06-37-1-1 is scheduled for October 30, 2006.

2. Signs and Markers

Mr. Collins came prepared to make corrections to the Property idenfication signs.

4.a Hydrologic Balance: Diversions

The site has received a lot of rain during the month and most recently on Monday and Tuesday of last week. Ditch UD-1 is ponding water and will not likely dry out this year.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Observed the mine plant pond, road side pond, auxillary pond, and the dryer pond all held water.

16.b Roads: Drainage Controls

Culverts along access roads were clear.